



STE BOKOUM s.a.r.l

Tel. +224 627 56 90 98/ +224 623 12 97 87

Email. bokoumd@gmail.com

01-07-2021

WWW.SOPAL.COM

RESTAURATION LIGNE DE CONDUITE EN MULTICOUCHE PEX

ARTICLES	UNITE	QUANTITES	PUV GNF	PRIX TOTAL
TUYAU PEX 12/16	ml	120	42,000	5,040,000
RACCORD COUDE 26	u	7	110,000	770,000
COLLE MINUTE	u	6	10,000	60,000
RACCORD FEMELLE EN POLY 32	u	1	20,000	20,000
RACCORD COUDE EN POLY 32	u	1	30,000	30,000
COLLIER 26	u	10	15,000	150,000
RACCORD DROIT T MALE 26	u	6	100,000	600,000
COLLIER 32	u	10	20,000	200,000
REDUCTEUR 26/20 INOX	u	2	30,000	60,000
BARRE DE TUYAU pvc 63	u	4	170,000	680,000
RACCORD FEMELLE EN POLY 25	u	5	18,000	90,000
CHEVILLE N 10	pq	1	25,000	25,000
COLLIER PVC 75	u	15	25,000	375,000
TOTAL				8,100,000

ALIMENTATION 8,100,000

MAIN D'OEUVRE 600,000

TOTAL 8,700,000

ARRETE LE PRESENT DEVIS A LA SOMME DE HUIT MILLIONS CENT MILLE FRANCS GUINEENS.

CB - Plomberie .
 (Renouveau de la plomberie dans
 la rampes d'accès au Sous-Sol)

CONFIRMÉ le 12 JUL. 2021